

Repair service for Generator fan Blades & Bearing PADs

Line	Description	Quantity	UOM
1	Repair Generator DE Pocket Journal Bearing for GT13E2 Unit (P/N: HTGD027132R0006, S/N: 500286); Qty: 1 set (2 Halves) .	1	Set
2	Repair Rotor 9A5 Generator Fan Blades (P/N: 127E3921P0002, H/L: MA013001430); Qty: 33 pcs.	33	Each
3	Repair Rotor 9A5 Generator Fan Blades (P/N: 127E3921P0001, H/L: MA013001430); Qty: 33 pcs.	33	Each

